

Inspection Software Systems
Pleasant Hill, CA

Row	Tube	% Wall Loss	ID	OD	Defect Code	Nominal Wall	Actual Wall Loss	Remaining Wall	LOCATION	COMMENT
1	1	0%			NRI	0.134	0.000	0.134		No Recordable Indications
1	2	28%			WLL	0.134	0.038	0.096	367.874in.	
1	3	40%			WLL	0.134	0.054	0.080	368.031in.	
1	4	29%			PIT	0.134	0.039	0.095	286.024in.	Pitting
2	1	17%			WLL	0.134	0.023	0.111	329.449in.	
2	2	17%			WLL	0.134	0.023	0.111	388.976in.	
2	3	10%			PIT	0.134	0.013	0.121	298.130in.	Pitting
2	4	38%			WLL	0.134	0.051	0.083	349.016in.	
2	5	13%			PIT	0.134	0.017	0.117	138.110in.	Pitting
2	6	30.5%			PIT	0.134	0.041	0.093	331.831in.	Pitting
3	1				OBS				331.063in.	Obstructed
3	2	0%			NRI	0.134	0.000	0.134		No Recordable Indications
3	3	19.9%			WLL	0.134	0.027	0.107	497.480in.	
3	4	22.4%			WLL	0.134	0.030	0.104	482.618in.	
3	5	28.4%			WLL	0.134	0.038	0.096	484.843in.	
3	6	21.7%			WLL	0.134	0.029	0.105	425.079in.	
3	7	21.4%			WLL	0.134	0.029	0.105	432.835in.	
4	1	20.7%			WLL	0.134	0.028	0.106	464.783in.	
4	2	22.3%			WLL	0.134	0.030	0.104	556.063in.	
4	3	45.2%			PIT	0.134	0.061	0.073	230.906in.	Pitting
4	4	19.2%			PIT	0.134	0.026	0.108	519.547in.	Pitting
4	5	19.2%			PIT	0.134	0.026	0.108	415.354in.	Pitting
4	6	15.3%			PIT	0.134	0.021	0.113	378.996in.	Pitting
4	7	14.2%			WLL	0.134	0.019	0.115	477.776in.	
4	8	20.7%			WLL	0.134	0.028	0.106	391.949in.	
5	1	44.4%			WLL	0.134	0.059	0.075	445.472in.	
5	2	37.7%			WLL	0.134	0.051	0.083	375.039in.	
5	3	25.3%			WLL	0.134	0.034	0.100	414.311in.	
5	4	41.8%			WLL	0.134	0.056	0.078	391.201in.	
5	5	40.4%			WLL	0.134	0.054	0.080	414.665in.	
5	6	32%			WLL	0.134	0.043	0.091	450.650in.	
5	7	22.4%			WLL	0.134	0.030	0.104	419.547in.	
5	8	22.7%			WLL	0.134	0.030	0.104	372.402in.	
6	1	47.1%			WLL	0.134	0.063	0.071	584.193in.	
6	2	25.5%			WLL	0.134	0.034	0.100	420.276in.	
6	3	38%			WLL	0.134	0.051	0.083	414.685in.	
6	4	19.6%			WLL	0.134	0.026	0.108	438.228in.	
6	5	22.3%			WLL	0.134	0.030	0.104	392.283in.	
6	6	19.8%			WLL	0.134	0.027	0.107	60.098in.	

Inspection Software Systems
Pleasant Hill, CA

Row	Tube	% Wall Loss	ID	OD	Defect Code	Nominal Wall	Actual Wall Loss	Remaining Wall	LOCATION	COMMENT
6	7	18%			WLL	0.134	0.024	0.110	162.047in.	
7	1	25.9%			WLL	0.134	0.035	0.099	391.713in.	
7	2	16.7%			WLL	0.134	0.022	0.112	213.524in.	
7	3	19.1%			WLL	0.134	0.026	0.108	407.047in.	
7	4	23.1%			PIT	0.134	0.031	0.103	576.496in.	Pitting
7	5	26.9%			WLL	0.134	0.036	0.098	407.598in.	
7	6	26.7%			WLL	0.134	0.036	0.098	459.193in.	
8	1	39.6%			WLL	0.134	0.053	0.081	391.043in.	
8	2	13.8%			WLL	0.134	0.018	0.116	499.232in.	
8	3	23.2%			WLL	0.134	0.031	0.103	417.795in.	
8	4	41.8%			WLL	0.134	0.056	0.078	438.346in.	